




# DOE HANFORD SITE - GROUNDWATER QUALITY DATA PLOTS

wellseries-200-299 WELL#=299-W7-11




WELLNAME=299-W7-11 WELLID=A5006	
Well Type=STANDARD	Well purpose=GROUNDWATER
Owner=DOE	Contact=BHI Well Adm Compliance=NON-COMPLIANT
X_coor= 566186.20	Y_coor= 137636.00 Datum=NAD83 Date Survey= 9/7/1991
Elevation= 208.003	Datum=NGVD29 Date Survey=09/7/91
Ref_Point_Desc=TOP OF PLATE	Ref_Point_side=N Contractor=KEH
Total Number of perforation Intervals=1	
NPERF#=1	Perf_top= 143.11 Bot= 137.01 MCas_size= 0.00 Perf_cuts= 0.00
Total Number of Screen Intervals=1	
Screen#=1	Screen_diam= 4.00 in Top= 64.47 Bottom= 70.71 m Slot_size= 0.01 in
	Screen_material=Stainless Steel
Total Number of Seals=5	
Seal#=1	Depth_top=-0.09 Bottom= 0.58 m Material=Concrete
Seal#=2	Depth_top= 0.58 Bottom= 6.10 m Material=Cement Grout
Seal#=3	Depth_top= 6.10 Bottom= 62.15 m Material=Granular Bentonite
Seal#=4	Depth_top= 62.15 Bottom= 63.37 m Material=Bentonite Pellets
More Information is at <a href="http://www.envirodataaccess.com/wellfiles/299-W7-11.htm">http://www.envirodataaccess.com/wellfiles/299-W7-11.htm</a>	


LABORATORY QUALIFIER FLAGS in HEIS are \*; >; B, C, D, E, J, L, P, Q, R, W, X, Y, and Z: Review Document. Main Flags are : J=Estimated value; L=Value between IDL and CRQL (estimated); T=Tentatively identified compound;  
EPA-IGR=EPA-Implementation Guidance for Radionuclides; WAC=Washington Administrative Code;

EXPLANATION: THICK FILLED BARS=Value Above Detection Limit; THIN BARS=Value Below Detection Limit; HATCHED BARS=Value With Data Qualifier Flag


## VOLATILE ORGANIC COMPOUNDS



## SEMI-VOLATILE ORGANIC COMPOUNDS




## METALS &amp; PHYSICAL PARAMETERS



LABORATORY QUALIFIER FLAGS in HEIS are \*, >, B, C, D, E, J, L, P, Q, R, W, X, Y, and Z: Review Document. Main Flags are : J=Estimated value:L=Value between IDL and CRQL (estimated):T=Tentatively identified compound:  
EPA-IGR=EPA-Implementation Guidance for Radionuclides: WAC=Washington Administrative Code:

EXPLANATION: THICK FILLED BARS=Value Above Detection Limit:THIN BARS=Value Below Detection Limit:HATCHED BARS=Value With Data Qualifier Flag

## METALS &amp; PHYSICAL PARAMETERS




LABORATORY QUALIFIER FLAGS in HEIS are \*; >; B, C, D, E, J, L, P, Q, R, W, X, Y, and Z: Review Document. Main Flags are : J=Estimated value; L=Value between IDL and CRQL (estimated); T=Tentatively identified compound;  
EPA-IGR=EPA-Implementation Guidance for Radionuclides; WAC=Washington Administrative Code:

EXPLANATION: THICK FILLED BARS=Value Above Detection Limit; THIN BARS=Value Below Detection Limit; HATCHED BARS=Value With Data Qualifier Flag


# DOE HANFORD SITE - GROUNDWATER QUALITY DATA PLOTS

wellseries-200-299 WELL#=299-W7-11

## PEST/PCB, HERB, & DIOXINS



## GENCHEM & ORGANICS & GENORGANICS



LABORATORY QUALIFIER FLAGS in HEIS are \*, >, B, C, D, E, J, L, P, Q, R, W, X, Y, and Z: Review Document. Main Flags are : J=Estimated value; L=Value between IDL and CRQL (estimated); T=Tentatively identified compound;  
EPA-IGR=EPA-Implementation Guidance for Radionuclides; WAC=Washington Administrative Code;

EXPLANATION: THICK FILLED BARS=Value Above Detection Limit; THIN BARS=Value Below Detection Limit; HATCHED BARS=Value With Data Qualifier Flag